EAST Search History

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	106	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:29
L2	0	L1 and nuclear adj fuel and rods	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:30
L3	348	non adj destructive and test \$3 and nuclear adj reactor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:33
L4	1	L3 and(acquiring or obtaining) near2 radiographic adj image \$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:35
L5	3	L3 and(acquiring or obtaining) and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:35
L6	2	L5 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:36
L7	0	L6 and(comparision or match \$3)and(stored or memory)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:36
L8	2	L6 and(comparision or match \$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:37
L9	0	L8 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:37

L10	0	L8 and(test\$3 or inspect\$3 or examining or detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:38
L11	0	L8 and(test\$3 or inspect\$3 or examining or detect\$3 or determining defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:38
L12	2	L8 and(test\$3 or inspect\$3 or examining or detect\$3 or determining defect or flaw or fault)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:38
L13	0	L12 and thickness adj measured	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:39
L14	1	L12 and thickness and measured	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:39
L15	0	L14 and porous and(areas or region)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:40
L16	0	L14 and porous and(area or region)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:40
L17	0	L14 and bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:41
L18	0	L14 and(nuclear adj fuel or rods)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:42
L19	0	L14 and(nuclear adj fuel or rod)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:42

L20	0	L14 and angles	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:43
L21	0	L14 and dimension	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:44
L22	4	((PHILIPPE) near2 (MAHE)). INV.	US-PGPUB; USPAT	OR	ON	2009/04/06 14:45
L23	1	L22 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:46
L24	1	L23 and(comparision or match \$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:47
L25	1	L24 and(test\$3 or inspect\$3 or examining or detect\$3 or determining defect or flaw or fault)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:47
L26	0	L25 and(@ad<"20031124" or @rlad<"20031124" or @prad<"20031124" or @ptad<"20031124")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:47
L27	О	L25 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:48
L28	6	(("(6154561") or ("2001055415") or ("5999636).pn.")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/04/06 14:49
L29	0	L28 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:49
L30	6	L28 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:51

S1	337	non-destructive and test\$3 and nuclear adj reactor	US-PGPUB; USPAT; EPO; JPO; DERWENT;	OR	ON	2009/04/06 13:38
S2	2	non-destructive and test\$3 and nuclear adj reactor and radiographic and digital adj image\$1	IBM_TDB US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:39
S3	10	non-destructive and test\$3 and nuclear adj reactor and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:43
S4	9	S3 and(@ad<"20031124" or @rlad<"20031124" or @prad<"20031124" or @ptad<"20031124")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:49
S 5	9	S3 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:50
S6	О	(test\$3 or inspect\$3 or examining)and(defect or flaw or fault)and welding adj joints and radiographic and digital adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:56
S7	286	(test\$3 or inspect\$3 or examining)and(defect or flaw or fault)and radiographic and digital adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:57
S 8	375	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:58
S9	307	\$3 and(@ad<"20031124" or @rlad<"20031124" or @prad<"20031124" or @ptad<"20031124")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:58
S10	257	S8 and @ad< "20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:59

S11	75	S10 and(comparision or match \$3)and(stored or memory)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:00
S12	0	S11 and assisting and rotating adj object and record\$3 adj image\$1 and digital adj mapp and welded adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:06
S13	0	S10 and assisting and rotating adj object and record\$3 adj image\$1 and digital adj mapp and welded adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:06
S14	375	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:10
S15	0	S14 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and radiographic adj image\$1 and welding adj joints and tubing	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:12
S16	1	S14 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and radiographic adj image\$1 and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:20
S17	106	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:21
S18	1	S17 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:22

4/6/09 2:56:21 PM

C:\ Documents and Settings\ SChawan\ My Documents\ EAST\ Workspaces\ 0513.wsp